



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210;  
Title: WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING;  
John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis,  
MO 63102, (314)621-5070

1/4

RECEIVED

JUL 26 2002

TECHNOLOGY CENTER 1700




FIG. 1



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 00-HL-19210;  
Title: WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING;  
John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis,  
MO 63102, (314)621-5070

2/4

RECEIVED  
JUL 26 2002  
TECHNOLOGY CENTER 1700




FIG. 2





FIG. 3



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210;  
Title: WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING;  
John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis,  
MO 63102, (314)621-5070

3/4



TECHNOLOGY CENTER 1700

RECEIVED  
JUL 26 2002

FIG. 4




FIG. 5



Applicant: Ali-Habib et al.; Serial No. 09/411,496; Atty. Dkt. No. 9D-HL-19210;  
Title: WASHING MACHINE BRAKE CAM ACTUATOR WITH INTERRUPTED RING;  
John S. Beulick, Armstrong Teasdale LLP, One Metropolitan Square, Suite 2600, St. Louis,  
MO 63102, (314)621-5070

4/4

RECEIVED  
JUL 26 2002  
TECHNOLOGY CENTER 1700




FIG. 6